

MATTELINC HWTH

MATTELINC HWTH

GIMICROELHKVL

5/24/79 MES. NO. DK-2036

TC: LARRY ATKINSON MATT ELL

CC: A. SECOR, C. PERRY, D. CHANDLER, R. NORWOOD (VISITING MATTEL)

1. WE HAVE RECEIVED TWO SETS OF LOGIC BOARD SHIELDS AND TWO CARTRIDGE SHIELDS. HOWEVER, SINCE THREE CARTRIDGES MUST BE SUBMITTED TO FCC WITH EACH UNIT, I AM SHORT FOUR SETS OF CARTRIDGE SHIELDS. PLEASE SHIP ASAP.
2. GTE SYLVANIA DID NOT NOTCH THE LOGIC BOARD ACCORDING TO DRAWING NC. 39-157, REV. D AS SPECIFIED. THE NOTCH INDICATED IN THE UPPER RIGHT HAND CORNER OF THE PRINT WAS NOT LOCATED PROPERLY. HOWEVER, THE SHIELDS WE RECEIVED ARE CORRECT. PLEASE ADVISE SYLVANIA.
3. THE CLEARANCE BETWEEN THE SHIELD AND THE LOGIC BOARD BEHIND THE UPPER LEFT HAND CONTROLLER CONNECTOR DOES NOT PROVIDE ENOUGH MARGIN. THE SHIELDS WE HAVE SHORT THE BOARDS IN THAT AREA. PLEASE CORRECT.

REGARDS,

KEN GREENBERG GI HIX

GIMICROELHKVL

MATTELINC HWTH

GIMICROELHKVL